

Canspec Group Inc.

12271 Horseshoe Way

Richmond, BC, Canada V7A 4V4

Phone: (604) 275-3800 (604) 275-3821

Materials Engineering and Testing A Rockwood Company

ISO 9002

PROJECT INSPECTION

CLIENT:

PRIMEX INDUSTRIAL COATINGS LTD.

140-12051 Horseshoe Way

Richmond, BC

V7A 4V4

JOB NO: A026050607

REPORT NO:

DATE:

July 10, 2002

PROJECT: Traficron Coatings

SPECIFICATION:

Client request

ENG. CONSULTANTS: ---

EQUIPMENT: Coated Panels

VENDOR:

Primex

P.O. NO: Verbal

ATTENTION:

Mr. Gregory Palamarz

REPORT BY:

D. Baron

DEFICIENCY SUMMARY:

July 05, 2002 - Testing at Canspec - D. Baron 1.0

1.1 Four coupons were tested for coating adhesion. The coupons were galvanized steel and treated with an adhesion-promoting primer, and coated as follows:

A. B

Traficron

F. G

Epoxy Primer and Traficron Plus

- 1.2 The results are shown in the attached tables.
- 1.3 The Traficron Plus without epoxy primer, and Traficon, systems performed well in both types of adhesion test.

Yours truly.

CANSPEC GROUP INC.

Reviewed by:

Dave Baron, AScT

T. Jones, P.Eng.

DB/TJ/smp

SCOPE OF SERVICES. The agreement of Carapec Group Inc. to perform services extends only to those services provided for in writing Under no circumstances shall such services extend beyond the performance of the requested services. It is expressly understood that all descriptions, comments and expressions of opinion reflect the opinions of deservations of Carapec based or information and assumptions supplied by the correctionarity and are not intended nor can they be construed as apprecentations of warrantes. Carapec is not assuming any responsibilities of the correctionarity menutacions, repair and use decisions as a result of the data or other information provided by Carapec. In no event shall Carapec's liability in respect of the services STANDARD OF CARES, in performance that STANDARD OF CARE: In performing the services provided, Cansper uses the degree, care, and skill ordinarily exercised under similar circumstances by others performing such services in the same or similar locality. No other warranty, expressed or implied, is made or intended by Cansper.

A02605-00607_01-01R1 P07905 Traferon achesion doc